

Notice for service campaign for SUBARU R1700i and R1100

Service campaign of portable generators R1700i and R1100
which is produced by Fuji Heavy Industries Ltd.

— Possibility of fuel leakage —

If these generators are used without sufficient ventilation, e.g. in small cabinets, caravans etc. for a long time, there is a possibility that the outlet nipple of the fuel tank may incur small cracks due to the unusually high temperature inside the generator. In very rare cases, this may result in a fuel leakage from the crack. Throughout Europe, only one case has occurred so far. Even though this risk occurs only in cases of misuse of these products and where the users do not adhere to the safety instructions contained in the owner's manual, for reasons of safety Fuji Heavy Industries Ltd. asks its customers to have the fuel tank exchanged.

Applicable models/serial numbers

R1700i



R1100



製品番号 号数
(PROD No. SER No.)



● **SER No (R1700i)**

3000003 ~ # 3000688
3010003 ~ # 3121505
6000001 ~ # 6017296
8000001 ~ # 8004382

● **SER No (R1100)**

4000001 ~ # 4000376
4010001 ~ # 4015102
7000001 ~ # 7002206
9000001 ~ # 9000487

Useful contact

Robin Europe GmbH

Call to

02161-6360 20 36

Business hours : Monday to Thursday : 9:00 to 16:30

Friday : 9:00 to 14:00

From November 15 , 2010